

















Aqua-Traxx® and Aqua-Traxx® PC Fittings				
Description	Use	Drawing	Tube Size	
			16 mm	22 mm
Tape Joiner	Used for joining or repairing tape lines		1014100	1014111
Tape × 10 mm Barbed Joiner	Used for joining tape to 10 mm poly pipe		1014101	
Tape × 13 mm Barbed Joiner	Used for joining tape to 13 mm poly pipe		FRC1398	
Tape × 10 mm Compression Joiner	Used for connecting tape to Durapol. Use 5 mm punch		1014102	
Tape Joiner × Barb	Used for connecting riser tube to tape		1014104 16 mm Barb × 16 mm Tape (use Drip-In plain poly 1015659)	1014112 20 mm Barb × 22 mm Tape (use Drip-In plain poly 1015660)
20 mm MBSP × Tape Director	Used for connecting the tape to valves or female threaded fittings		1014105	1014113
10 mm Compression × Tape In-Line Tap	Used to turn off supply to tape lines. Used when connected to Durapol		1014106	
16 mm Barb × Tape In-Line Tap	Used to turn off supply to tape lines. Used when connected to poly tube		1014107 (use Drip-In plain poly 1015659)	
25 mm BSPF × Tape Tee	Used to connect tape lines to male threaded riser		1014108	
Tape Tee	Used for connection of tape × tape × tape		1014109	
Two Stage Layflat Adaptor	Used for connecting Aqua-Traxx tape to Lay-Flat tubing (16 mm diameter hole required)		1014099 (double spigot)	1014115
One Stage Layflat Adaptor	Used for connecting Aqua-Traxx tape to Lay-Flat tubing (19 mm diameter hole required)		1014103	
Drip-In Tubing	Used for riser tube from the uPVC submains (Plain tube, no emitters)		1015659 (OD 16 mm) (ID 14 mm) 450 m roll	1015660 (OD 20 mm) (ID 18 mm) 300 m roll
Grommet Take-Off Complete	Used for connecting Aqua-Traxx via plain Drip-In riser to uPVC submains (min 32 mm size)		1015678 (hole saw 5/8")	1015681 (hole saw 5/8")
Vent Valve End Flushing Valve	Used to expel air on start up, introduce air on shut down. Connected to the tape with a tape director MHT-06-LS (16 mm) or MHT-09-LS (22 mm)		1014811 with MHT-06-LS	1014811 with MHT-09-LS
End Plug	Used to seal the ends of driplines		1014110	